

REPORT OF CHANNEL CONDITIONS 100 TO 400 FEET WIDE <i>(EP 1130-2-520)</i>						PAGE 1 OF 1 <hr/> DATE 14 August 2008	
TO: Navigation Interests				FROM: U.S. Army Engineer District, Baltimore P.O. Box 1715 Baltimore, Maryland 21203-1715			
RIVER/HARBOR NAME AND STATE Smith Island					MINIMUM DEPTHS IN CHANNEL ENTERING FROM SEAWARD		
NAME OF CHANNEL	DATE OF SURVEY	AUTHORIZED PROJECT			LEFT OUTSIDE QUARTER <i>(feet)</i>	MIDDLE HALF <i>(feet)</i>	RIGHT OUTSIDE QUARTER <i>(feet)</i>
		WIDTH <i>(feet)</i>	LENGTH <i>(miles)</i>	DEPTH <i>(feet)</i>			
Levering Creek Station 0+000 to 1+000 & Station 3+000 to 7+647	15/Jul/200	60	1	6		1	
REMARKS <i>(Continue on reverse)</i> All depths refer to MLLW for the 1983-2001 tidal epoch This information represents the results of surveys made on the dates indicated (15 July 2008) and can only be as indicating the general conditions at that time. Length of channel is reported to nearest mile (actual length is 1.07 miles). Middle half equals minimum depth in full channel. MH=E1592734.38, N120385.13 (0.9')							